







Refurbishment RN1. North Interamerican Highway

Barranca and Limonal, Costa Rica / 2015-2017

Structural type
Characteristics
Owner
Client
Scope

truss bridge, steel beams and concrete beams
highway 50.5 km. Extension to 4 lanes, renewal of pavement, refurbishment and design of structures
Banco Interamericano de Desarrollo
Unidad Ejecutora del Programa PIT
detailed design



Description



C/ Barquillo 23, 2º | 28004 Madrid | España
T. (+34) 917 014 460 | F. (+34) 915 327 864
www.fhecor.com | fhecor@fhecor.es